



# Data Sheet

UT8804E Benchtop Digital Multimeter



# Main Features

• Reading resolution: 4%, maximum reading 59999

• Measuring rate: 2 reading/s

• DC voltage range: 60mV~1000V

DC current range: 600µA~20A

• AC voltage range: 60mV~1000V (True-RMS)

• AC current range: 600µA∼20A (True-RMS)

• Resistance range:  $600\Omega \sim 60M\Omega$ 

Capacitance range: 6nF∼60mF

• Conductivity range: 60ns

• Frequency measurement range: 60Hz~60MHz

• Duty cycle measurement range: 10%~90%

• Mathematical operation: maximum, minimum, average, peak, comparative measurement, trend chart

• Interface: USB device, It can be connected to the upper computer control software

• Frequency response: 100KHz

• Data record: 20000 groups

• LPF low pass filter function

• Support global mains voltage

# Multimeter Panel



- ①LCD display ②Power switch ③Input interfaces ④Menu operating buttons
- ⑤Measure and auxiliary function buttons ⑥Function selector knob



- ①GND ②Lockhole ③Current measurement fuse ④USB Device interface
- ⑤AC voltage selector ⑥Power supply interface ⑦Power supply fuse

## **Product Introduction**

UT8804E is a 4%-count benchtop digital multimeter (hereinafter referred to as the meter) with auto range, color display and true RMS measurement functions. Its circuit design adopts large scale integrated circuit A/D conversion, microprocessor, multifunction measurement and high stable thin-film resistor manufacturing technology, which makes it a digital multimeter with superior performance. The meter can be used to measure AC/DC voltage, AC/DC current, resistance, conductance, diode, continuity, capacitance, temperature, frequency, pulse width, etc. Besides, it also has data hold, max/min/ average value measurement, comparison function measurement, relative value measurement, peak detection, tendency chart capture, and up to 20000 data recording/readback functions. The integrated 4.3-inch color display provides multi-level, comprehensive measurement results with both readings and tendency charts, Which makes the result at a glance.

#### Display accuracy

UT8804E digital multimeter can display 4 % digits (59999), It can provide you high-precision and accurate result display. Its simulation bar makes the display of measurement results more intuitive. 4.3 inch full-color display, giving you a better visual experience.



#### Comparison function

UT8804E digital multimeter has comparison function. For the index range required by batch device test, UT8804E will help you automatically identify unqualified devices and give an alarm.



#### Extreme value function

The UT8804E digital multimeter has the function of maximum and minimum value statistics. This function can help you find out the maximum output, the minimum output and the average value. Besides, it can also give the time when the extreme value appears and the total measurement time slot. The statistical method is applicable to all testable items such as voltage, current, resistance and capacitance.



#### Multiple measurement items optional

For each test item, multiple test parameters can be selected to meet your test requirements.

Additional secondary parameters can be added to make the measurement more specific, while displaying the main parameters.





#### Reference value mode

Press REL to set the test reference value, which can be set according to the error or deviation of the measured items, Then you can see the calculation result relative to the reference value on the display, The reference value and original measured value are also displayed for reference.



#### Data record

In addition to the data saving function, the UT8804E digital multimeter also has the recording function. You can record all the measured data captured in the test according to the measurement needs. During the recording process, REC • will show that the recording is in progress, and will display the number of samples recording duration, extreme value, average value and other information.



#### Historical data analysis

The recorded data record will have full-time statistical data and intuitive trend chart when looking back, which is convenient for you to check the abnormal data in the time slot. The value at a certain time point can also obtained by adjusting the cursor in the trend chart.





#### Remote operation

UT8804E digital multimeter can be connected to the upper computer. After installing the driver software, it can realize remote viewing and control, and observe historical data and trend chart in real time.



# **Technical Specification**

#### **EXPLAIN:**

Accuracy: ±(% of reading + digits)

If the ambient temperature changes by ±5 °C, the accuracy will not be used until 2 hours later

The calibrator is 1 year

Ambient temperature: 23 °C ±5 °C

Ambient humidity:≤75% RH

Temperature coefficient: 0.1x(specified accuracy)/ C (<18 C or>28 C)

Input impedance: About  $10M\Omega$  Overload protection: 1000V

AC Display: True RMS, applicable to 10%~100% of the range

When the measured current is Close to 20A, each measurement time should be less than 30s and the

rest interval should be more than 10 minutes!

Range	Resolution	Accuracy					
		45 <b>-</b> 1kHz	1	k-10kHz	10k <b>-</b> 20kHz		20k <b>-</b> 100kHz
60mV	0.001mV	±(0.6%+60)	±(	1.2%+60)	±(3%+60)		±(4%+60)
600mV	0.01mV	±(0.3%+30)	±(	1.2%+40)	±(3%+40)		±(4%+40)
6V	0.0001V	±(0.3%+30)	±(	1.2%+40)	±(3%+40)		±(4%+40)
60V	0.001V	±(0.3%+30)	±(	1.2%+40)	±(3%+40)		±(4%+40)
600V	0.01V	±(0.4%+30)	±(	1.2%+40)	±(3%+40)		for reference only
1000V	0.11/	45-1kHz	1k	1k-5kHz 5k-10kHz			10k <b>-</b> 100kHz
	0.1V	±(0.6%+30)	±(	3%+40)	±(6%+40)		for reference only
DC Voltage							
Range	Resolution	Accuracy	re	marks			
60mV	0.001mV	±(0.025%+20)	This gear requires the relative mode (REL) function to compensate for bias				
600mV	0.01mV	±(0.025%+5)					
6V	0.0001V	±(0.025%+5)					
60V	0.0001V	±(0.025%+5)					
600V	0.01V	±(0.003%+5)					
1000V	0.1V	±(0.003%+5)					
AC Voltage	e + DC Voltage						
Range	Resolution	Accuracy					
	•	50 <b>-</b> 1kHz		1k-10	)kHz	1	0k <b>-</b> 35kHz
60mV	0.001mV	±(1%+80)		±(3%+40)		±	:(6%+40)
600mV	0.01mV	±(1%+80)		±(3%+40)		±	:(6%+40)
6V	0.0001V	±(1%+80)		±(3%+40)		±	:(6%+40)
60V	0.001V	±(1%+80)		±(3%+40)		±	:(6%+40)
600V	0.01V	±(1%+80)		for reference only		f	orreference only
1000V	0.01V	±(1.2%+80)		forre	eference only	f	orreference only
AC curren	t						
AO CUITCII							

		(5.4)	41.4011		
		45-1kHz	1k-10kHz		
600uA	0.01uA	±(0.6%+40)	±(1.2%+40)		
6000uA	0.1uA	±(0.6%+20)	±(1.2%+40)		
60mA	0.001mA	±(0.6%+40)	±(1.2%+40)		
600mA	0.01mA	±(0.6%+20)	±(0.6%+20)		
6A	0.0001A	±(1%+20)	±(3%+40)		
10A	0.001A	±(1%+20)	±(3%+40)		
DC current	Resolution	Acquired			
Range		Accuracy			
600uA	0.01uA	±(0.08%+20)			
6000uA	0.1uA	±(0.08%+10)			
60mA	0.001mA	±(0.08%+20)			
600mA	0.01mA	±(0.15%+10)			
6A	0.0001A	±(0.3%+10)			
10 A	0.001A	±(0.5%+10)			
AC current +   Range	Resolution	Accuracy	_		
Range	Resolution		1, 10,11-		
000 4	0.1.1	50-1kHz	1k-10kHz		
600uA	0.1uA	±(0.8%+40)	±(2.0%+40)		
6000uA	0.1uA	±(0.8%+20)	±(2.0%+40)		
60mA	0.001mA	±(0.8%+40)	±(2.0%+40)		
600mA	0.01mA 0.0001A	±(0.8%+20) ±(1.2%+20)	±(2.0%+40) ±(3%+40)		
10 A	0.0001A 0.001A		±(3%+40) ±(3%+40)		
Resistance	0.001A	±(1.2%+20)	±(3%+40)		
Range	Resolution	Accuracy	Remarks		
600Ω	0.01Ω	±(0.05%+10)	In the REL state		
6kΩ	0.0001kΩ	±(0.05%+2)	III the REL State		
60kΩ	0.0001kΩ	±(0.05%+2) ±(0.05%+2)			
600kΩ	0.001κΩ	±(0.05%+2)			
6ΜΩ	0.0001ΜΩ	±(0.05%+2) ±(0.3%+10)			
60ΜΩ	0.00011Ω	±(2%+10)	Required humidity < 50%		
Conductance		-1-70	The state of the s		
Range	Resolution	Accuracy	Remarks		
6nF	0.001nF	±(3%+10)			
60nF	0.01nF	±(2.5%+5)			
600nF	0.1nF	±(2%+5)			
6uF	0.001uF	±(2%+5)			
60uF	0.01uF	±(2%+5)			
600uF	0.1uF	±(2%+5)			
6mF	6mF	±(5%+5)			
60mF	10uF	Not specified			
Temperature					
Range	Resolution	Accuracy	Remarks		
-40°C~40°C	1°C	±(2%+30)			
40°C~100°C	1°C	±(1%+30)	Temperature concert the appropriate are point		
100°C~1000°C	1°C	±2.5%	Temperature sensor: the accessories are point type K thermocouple, which is only applicable to the measurement of temperature below 230°C.		
-40°F~104°F	1°F	±(2.5%+50)			
104°F~752°F	1°F	±(1.5%+50)			
752°F~1832°F	1°F	±2.5%			
Temperature					
Range	Resolution	Accuracy	Remarks		
- 9-			I		

UT8804E Datasheet

-40°C~40°C	1°C	±(2%+30)			
40℃~100℃	1°C	±(1%+30)	Temperature sensor: the accessories are point type K		
100°C~1000°C	1°C	±2.5%			
-40°F~104°F	1°F	±(2.5%+50)	thermocouple, which is only applicable to the measurement of temperature below 230°C.		
104°F~752°F	1°F	±(1.5%+50)	of temperature below 200 c.		
752°F~1832°F	1°F	±2.5%			
Frequency					
Range	Resolution	Accuracy	Remarks		
60Hz	0.001Hz	±(0.02%+8)			
600Hz	0.01Hz	±(0.01%+5)			
6kHz	0.0001kHz	±(0.01%+5)			
60kHz	0.001kHz	±(0.01%+5)	Input amplitude requirements:		
600kHz	0.01kHz	±(0.01%+5) 10Hz~30MHz: 600mV≤a≤30Vrm			
6MHz	0.0001MHz	±(0.01%+5)			
60MHz	0.001MHz	±(0.01%+5)			
Duty Ratio					
Range	Resolution	Accuracy	Remarks		
10%~90% (10Hz~2kHz)	0.01	±(1.2%+30)	Rise time:<1us, the signal is centered on the triggering level.		
Pulse Width					
Range	Resolution	Accuracy	Remarks column		
250m	0.001mS~ 0.01mS	±(1.2%+30)	10Hz ~ 60KHZ, pulse width > 2us. The pulse width range is determined by the frequency of the signal. Input amplitude requirements: 1vpp ≤ a ≤ 20vpp.		
Continuity Meas	urement				
Range	Resolution	Remarks			
-1))	0.010	The OCV is about 3V; Short circuit alarm: If the resistance is<10 $\Omega$ , the buzzer goes off continuously; If the resistance is>50 $\Omega$ , the buzzer does not go off. Open circuit alarm: If the resistance is>50 $\Omega$ , the buzzer goes off continuously; If the resistance is<10 $\Omega$ , the buzzer does not go off.			
Diodes Measure	ment				
Range	Resolution	Remarks			
*	0.0001V	The OCV is about 3V, and the measurable forward voltage drop value of the PN junction is about 3V.  When the buzzer is activated, short beep indicates the normality of the PN junction; continuous beep indicates the short circuit of the PN junction.  The typical voltage of silicon PN junction is about 0.5 to 0.8V.			







<sup>\*</sup>The UTD8804E have been certified by CE, cETLus.

# Warranty

Three-years warranty, excluding probes and accessories.

Please visit https://instruments.uni-trend.com/list\_190/65.html to learn more information.

To protect your investment, please purchase from UNI-T official authorized global distributors.

### Find a Distributor

Find an authorized distributor here: https://instruments.uni-trend.com/Network

## Contact UNI-T

E-mail: info@uni-trend.com

Test & Measurement Instruments Website: instruments.uni-trend.com

UNI-T Corporate Website: www.uni-trend.com

UNI-T group maintains a wide products category includes Digital Test & Measurement instruments, Field Testing Meter, Infrared thermal imaging products. As early as 2008, we continue to introduce self-developed Digital Test and Measurement instruments to the market and have made remarkable achievements. At present, we have formed a variety of product lines of Oscilloscope, AWG, Spectrum Analyzer, Bench Multi-meter, Power Supply, DC Load, Power Meter, LCR Meter, Micro Ohm Meter and Data logger. We have separated instruments sub-sites, instruments.uni-trend.com, on the basis of the original website www.uni-trend.com, in order to be more targeted to provide customers with better service and value.

UNI-TMKT/TMI/SCAL-2111-013 Instrument.uni-trend.com

